

ATTORNEY'S DOCKET:
004578.1106

PATENT NO:
US 6,993,315 B1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Gary Frazier
U.S. Patent No.: US 6,993,315 B1
Issue Date: January 31, 2006
Serial No.: 09/716,417
Filing Date: November 21, 2000
Confirmation No.: 8188
Title: SUPER-REGENERATIVE MICROWAVE DETECTOR

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Dear Sir:

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. The Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,
BAKER BOTTS L.L.P.
Attorneys for Applicant


Bradley P. Williams
Reg. No. 40,227

Date: 9/12/07
Customer No.: 45507
Phone: (214) 953-6447

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Patent No.: US 6,993,315 B1
Dated: January 31, 2006
Inventor(s): Gary Frazier

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, Line 35:

After "a low noise" delete ">1000 Hz" and insert – **100 GHz --**.

Column 4, Line 4:

After "an" delete "RID" and insert – **RTD --**.

Mailing Address of Sender:

Baker Botts L.L.P.
2001 Ross Avenue, Suite 600
Dallas, Texas 75201-2980

Patent No. US 6,993,315 B1

Form PTO-1050